


PATIENT SAFETY ALERT


Neural connectors

Don't be caught with equipment that doesn't work!

TRADITIONAL LUER CONNECTOR



NEW ISO 80369-6 CONNECTOR (NRFIT™)



- The change to an internationally agreed connector for neural and nerve block applications, ISO 80369-6, is soon to be deployed.
- The timeframe for introduction is not fixed and will be determined by product availability in Australia and New Zealand.
- Most devices with Luer and proprietary non-Luer connectors now in use will cease to be produced.
- The change affects a wide distribution of users within your organisation – many more than you may be aware of.
- Heads of departments, clinicians and procurement officers need to be aware of these changes.

It is crucial that ad hoc introduction of this equipment is avoided.

For more information, including a list of impacted equipment, please visit www.anzca.edu.au/front-page-news/safety-alert-neural-connector-changeover